

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2026

Submitted Date:

04/07/2026

Document Number:

717300898

FIELD INSPECTION FORM

Loc ID 331359 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261022	WELL	PA	05/16/2025	GW	123-20557	HRS-GARDNER 13-11	PA
331359	LOCATION	CL			-	HRS-GARDNER-62N67W 11SWSW	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 261022 Type: WELL API Number: 123-20557 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 331359 Type: LOCATION API Number: - Status: CL Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
As outlined on ECMC form 19 spill report Doc #404604643 received on 04/03/2026: While conducting wellhead and flowline removal activities at the HSR-Gardner 13-11 Wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. Assessment activities are ongoing. The wellhead and flowline are being permanently removed.	maclarej	04/07/2026
Well is plugged and abandoned (HRS Gardner 13-11); ECMC form 42 notice of start of plugging operations doc #404169898 received on 04/17/2025. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #404225312 received on 06/02/2025. No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	04/07/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300904	Location; PA well (No FL risers)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7507114
717300905	Location; view west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7507115