

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2026

Submitted Date:

04/07/2026

Document Number:

716302140

FIELD INSPECTION FORM

Loc ID 308028 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
B ZECHES, GIENA		gzeches@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260244	WELL	PR	09/21/2001	CBM	071-07410	APACHE CANYON 19-02V	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Ancillary equipment	# 1				
		Comment: <input type="text"/>			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Gas Meter Run	# 1				
		Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Bradenhead	# 1				
		Comment: <input type="text"/>			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Progressive Cavity	# 1				
		Comment: <input type="text"/>			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Deadman # & Marked	# 5				
		Comment: <input type="text"/>			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Prime Mover	# 1				
		Comment: <input type="text"/>			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Vertical Separator	# 1				
		Comment: <input type="text"/>			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Other	# 1				
		Comment: 30 bbl produced water tank.			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Compressor	# 1				
		Comment: Vacuum pump observed on well without ECMC approval.			

Corrective Action:	Provide ECMC with documentation showing approval of use of vacuum pump PER RULE 432. CA DATE 4/23/2026.	Date:	04/23/2026
--------------------	---	-------	------------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 260244 Type: WELL API Number: 071-07410 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/19/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 268876 Lat: 37.075531 Long: -104.926235

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	268876	1121975	

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Date: 4/7/2026 Time: 14:07 Operator: Ogris Operating LLC.10758 Location: APACHE CANYON 19-02V API# 05-071-07410 County: Las Animas County. While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: VACUUM PUMP W/OUT APPROVAL, RULE432, CA DATE 4/13/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	04/07/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716302141	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7507169