

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2026

Submitted Date:

04/07/2026

Document Number:

718000084

**FIELD INSPECTION FORM**

Loc ID 489500 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Chevron Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489505	TANK BATTERY	AC	03/11/2025		-	CECIL 32-34 TANK	EI
489515	SPILL OR RELEASE	CL	05/13/2025		-	CECIL-6 7N64W 32 SESW	EI
489659	SPILL OR RELEASE	CL	05/13/2025		-	CECIL-67N64W 32 SESW	EI

**General Comment:**

[ECMC Environmental Inspection of decommissioned tank battery/production facility, Remediation Project 33209. All production facilities have been removed. It appears that reclamation has begun on a portion of the Location.](#)

**Inspected Facilities**

Facility ID: 489505 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489515 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489659 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: Remediation Project 33209: Operator's last Supplemental Form 27 (Document# 404362064) dated 10/22/2025 was denied. No data for this location have been reported since 4/29/2025. Operator is overdue to complete site investigation and remediation of Reported Releases 489515, 489659. Site investigation was approved to have been completed by 7/30/2025.

Corrective Action: Submit Supplemental Form 27 with all site investigation and remediation conducted to date, documentation that the vertical and horizontal extents of the Releases have been defined, and documentation that the threat to groundwater has been investigated.

Date: \_\_\_\_\_

No corrective action date is provided because these actions are overdue.

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718000085	Cecil32-24TANK_LocationPhoto_04072026	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7507354">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7507354</a>