

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2026

Submitted Date:

04/01/2026

Document Number:

701104652

**FIELD INSPECTION FORM**

Loc ID 312645 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	<a href="#">QB Inspection mail box</a>
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222078	WELL	PR	11/20/1994	GW	077-08680	DEBEQUE 8-13	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
 Tank paint has deterioration and areas of rust.  
 Staining from top of tank down the side of tank.  
 Staining from thief hatch down the side of tank.  
 Staining build up around man hatch plate.  
 Fluid over flow from PRV (Pressure relief valve) on top of tank.  
 Corrective actions :Clean staining from tank.  
 Inspect, repair and maintain integrity of tank. Inspect man hatch plate bolts and seal. Inspect PRV is in working order from over flow of fluids.  
 Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.  
 CA Date 4/17/2026  
 Warning sign is peeling and danger sign is faded.  
 Install sign to comply with Rule 605.g.  
 CA Date 5/2/2026

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Warning sign is peeling and danger sign is faded.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	05/02/2026

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:	#		corrective date
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:	Tank paint has deterioration and areas of rust. Staining from top of tank down the side of tank. Staining from thief hatch down the side of tank. Staining build up around man hatch plate. Fluid over flow from PRV (Pressure relief valve) on top of tank.					
Corrective Action:	Clean staining from tank. Inspect, repair and maintain integrity of tank. Inspect man hatch plate bolts and seal. Inspect PRV is in working order from over flow of fluids. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.				Date:	04/17/2026

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 222078 Type: WELL API Number: 077-08680 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404605010	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7502045">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7502045</a>
701104653	Flowline integrity inspection 701104652 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7502042">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7502042</a>