

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2026

Submitted Date:

04/01/2026

Document Number:

709100641

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Ryan Finley		rfinley@entradainc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488529	SPILL OR RELEASE	AC	12/02/2024		-	Bobcat 11 Flowline	EI

General Comment:

On March 26, 2026, ECMC staff Krystal Heibel, Kilian Collins, and Alex Ahmadian conducted an inspection at the Bobcat 11 Flowline (Facility ID 488529).

Spill ID #488529 is active and associated with this location.

Form 19-Initial (Doc# 404000010) was submitted on November 19, 2024, Form 19-S (Doc# 404011888) was submitted on December 2, 2024, and no other Form 19-S submittals have been received to date.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 488529 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Distressed vegetation observed.

Corrective Action: Operator shall conduct an investigation via grab confirmation soil sampling to characterize the soils and potential E&P Waste impacts. Operator shall submit a Form 19-S requesting to continue this investigation in a Remediation Project (Form 27) since it is greater than 90 days since the discovery of the spill/release. Date: 04/08/2026

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404605189	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7502229
709100642	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7502222