

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2026

Submitted Date:

04/08/2026

Document Number:

718300138

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Anderson, Laurel On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
Chew, Cullen	205-914-4843	cchew@kpk.com	Environmental Coordinator
Robinson, Taylor		taylor.robinson@state.co.us	
Silva, Mani	303-833-5670	msilva@kpk.com	Manager of Production Operations
Kauffman, KPK	720-868-9848	cogcc@kpk.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	
Kirschner, Steven		steven.kirschner@state.co.us	
Watzman, Ross	301-213-1724	rwatzman@kpk.com	All Inspections
Burn, Diana		diana.burn@state.co.us	
Motisi, Dan	303-909-0875	dmotisi@kpk.com	Environmental Geologist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159787	LOCATION	AC			-	Facility 5	EI
492917	SPILL OR RELEASE	AC			-	Facility 5 Gas Line	EI

General Comment:

This is an Environmental Field Inspection to provide the laboratory analytical report from ECMC's sampling of oil from the sight glass on KP Kauffman Company Inc's (KPK) horizontal separator at the Facility 5 Tank Battery (Location ID 159787) on April 3rd, 2026. Any necessary corrective actions will be provided on a separate Field Inspection Report.

THIS IS ONLY TO PROVIDE ANALYTICAL. A more detailed inspection will follow.

Inspected Facilities

Facility ID: 159787 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 492917 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Inspection Date: 4/3/2026 Weather: Partly cloudy, windy with ~20mph gusts, ~40F PPE: Level D & FR Clothing	andersoln	04/08/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718300141	2026_0403_Laboratory Analytical Report-260315606 DIG-043485-043486	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7508257