

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2026

Submitted Date:

04/08/2026

Document Number:

718300139

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kirschner, Steven		steven.kirschner@state.co.us	
Chew, Cullen	205-914-4843	cchew@kpk.com	<a href="#">Environmental Coordinator</a>
Brown, Kari		kari.oakman@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Motisi, Dan	303-909-0875	dmotisi@kpk.com	<a href="#">Environmental Geologist</a>
Silva, Mani	303-833-5670	msilva@kpk.com	<a href="#">Manager of Production Operations</a>
Graber, Nikki		nikki.graber@state.co.us	
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
Watzman, Ross	301-213-1724	rwatzman@kpk.com	<a href="#">All Inspections</a>
Robinson, Taylor		taylor.robinson@state.co.us	
Kauffman, KPK	720-868-9848	cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482754	TANK BATTERY	AC			-	Consolidation Facility 7	EI
492917	SPILL OR RELEASE	AC			-	Facility 5 Gas Line	EI

**General Comment:**

This is an Environmental Field Inspection to provide the laboratory analytical report from ECMC's sampling of condensate from the sight glass on KP Kauffman Company Inc's (KPK) vertical separator at the Consolidation Facility 7 (Tank Battery Facility ID 482754) on April 3rd, 2026. Any necessary corrective actions will be provided on a separate Field Inspection Report.

**THIS IS ONLY TO PROVIDE ANALYTICAL. A more detailed inspection will follow.**

**Inspected Facilities**

Facility ID: 482754 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 492917 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Inspection Date: 4/3/2026 Weather: Clear, windy, ~50F PPE: Level D & FR Clothing	andersoln	04/08/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718300142	2026_0403_Laboratory Analytical Report-260315606 DIG-043485-043486	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7508258">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7508258</a>