

Inspection Photos

API: 071-09374

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/7/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the access road that remains per approved variance.



Inspection Photos



Photo 2. Facing west climbing up the road. This area has eroded and needs to be repaired and stabilized.



Inspection Photos



Photo 3. Facing east back down the road side. This area could use additional reseeding to establish vegetation.



Inspection Photos



Photo 4. Facing west along the access road. Stormwater is directed down the length of the road side causing the erosion in the previous photo.



Inspection Photos



Photo 5. There is stormwater runoff causing erosion at this point which is directed down the road.



Inspection Photos



Photo 6. Facing northwest at the location that remains per approved variance.



Inspection Photos



Photo 7. Facing west along the fill slope.

