

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 5228 From entrance to location



Photo # 5229 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 5230 Location



Photo # 5231 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 5232 Location



Photo # 5233 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 5234 Tank battery lacks required signage



Photo # 5235 Tank battery lacks required signage

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 5236 Tank battery lacks required signage



Photo # 5237 Tank battery lacks required signage

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 5238 Open ended load line