

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2026

Submitted Date:

04/02/2026

Document Number:

708908834

**FIELD INSPECTION FORM**

Loc ID 335773 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 19 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	
Longworth, Mike		mike.longworth@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270316	WELL	PR	01/01/2026	GW	045-09525	CHEVRON 23C-17D	PR
270317	WELL	PR	01/01/2026	GW	045-09526	CHEVRON 23A-17D	PR
270318	WELL	SI	08/01/2022	GW	045-09527	CHEVRON 22C-17D	SI

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank label damaged & illegible		
Corrective Action:	Comply with CECMC Rule 605		Date: 05/02/2026
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Barbed wire fence		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 3		
Comment:	No form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Unused flowlines lack lockout tagout (OOSLAT)		
Corrective Action:	Comply with CECMC Rule 1101	Date:	04/09/2026

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	Unknown - Tank label damaged & illegible
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 270316 Type: WELL API Number: 045-09525 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270317 Type: WELL API Number: 045-09526 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270318 Type: WELL API Number: 045-09527 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut In - Last produced July 2022

OUT OF SERVICE DESIGNATION - FORM 6A document # 403150040

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
Gravel						Sparse to none in most areas
Berms						
Rip Rap						
		Check Dams				
		Culverts				
		Gravel				Sparse to none
		Compaction				Light compaction
		Sediment Traps				
		Berms				
Ditches						
		Rip Rap				
		Ditches				
Compaction						Light compaction in some areas

Comment:

Corrective Action:

Date:

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a>                      On 04/01/2026 at approximately 12:34 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at QB ENERGY OPERATING LLC CHEVRON 23C-17D (PARACHUTE CREEK 4 696)                      Location # 335773 in Garfield County Colorado.                      Please refer to inspection/audit 708907472 conducted on 09/17/2025 &amp; inspection/audit 701104470 conducted on 01/22/2026, previous corrective actions have been completed.                      Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area.                      Location is approximately 279 yards from Parachute Creek.                      While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. Signs/Marker - Tank label damaged &amp; illegible - Comply with Rule 605 with a CA date of 05/02/2026</li> <li>2. Equipment - Unused flowlines lack lockout tagout (OOSLAT) - Comply with Rule 1101 with a CA date of 04/09/2026</li> </ol> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p>	smelserw	04/02/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404606453	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7503281">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7503281</a>
708908836	Inspection/Audit 708908834 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7503279">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7503279</a>
708908837	Inspection/Audit 708908834 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7503280">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7503280</a>