

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2026

Submitted Date:

04/02/2026

Document Number:

719700555

FIELD INSPECTION FORM

Loc ID 302509 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299099	WELL	TA	04/01/2020	GW	123-29254	BASHOR STATE AA 16-02	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Yellow LTSI tag posted. *Affix sign to well or fencing.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 1.) Undesirable vegetation at wellsite(s). (Weeds). Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control undesirable vegetation around wellsite(s). Comply with Rule 606.c. (14 days). 04/17/2026. See photo(s) #1, 2.		Date: <u>04/17/2026</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 299099 Type: WELL API Number: 123-29254 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-Out, Tagged-Out | LOTO.
Yellow LTSI tag posted at well.
ECMC records last prod: 06/2016.

Form 4 on file. TA date: 01/29/2019. Approved.
Form 6A on file. Out-of-Svc Designation. Approved.
Date ceased prod: 01/01/2015.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 06/05/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>Comment 1: This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.486284 / -104.432985</p> <p>Abandoned Centralized Battery formerly served 8 Location IDs (302510, 302509, 302511, 302512, 302513, 302517, 302521, 302540). (Well(s): 5: Temporarily Abandoned TA; 3: Plugged & Abandoned PA).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700553 and/or Location ID #302512 for TA Well(s) info. B.) Field Audit Report doc. #719700555 and/or Location ID #302509 for TA Well(s) info. C.) Field Audit Report doc. #719700557 and/or Location ID #302510 for TA Well(s) info. D.) Field Audit Report doc. #719700559 and/or Location ID #302511 for TA Well(s) info. E.) Field Audit Report doc. #719700561 and/or Location ID #302521 for TA Well(s) info. F.) Field Audit Report doc. #719700563 and/or Location ID #302517 for PA Well(s) info.</p>	evinsb	04/02/2026

<p>Comment 2: CECMC Audit Report Synopsis:</p> <p>On MON 03/30/2026 at approximately 15:37 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR STATE AA-66N63W/16NWNE Location ID: 302509 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.486284 / -104.432985</p> <p>*CORRECTIVE ACTION ITEM(s): 1 1.) Refer to pg 2, "Good Housekeeping" section of this report.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	<p>evinsb</p>	<p>04/02/2026</p>
---	---------------	-------------------

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404606924	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504071
719700556	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504065