

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2026

Submitted Date:

04/09/2026

Document Number:

719700619

**FIELD INSPECTION FORM**

Loc ID 413776 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412013	WELL	TA	04/01/2020	OW	123-30351	AURORA USX AB 25-11P	PA

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

**Inspected Facilities**

Facility ID: 412013 Type: WELL API Number: 123-30351 Status: TA Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: JMR Services Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 2073'-795'-0' Cement Volume (sx): 277 sxs

Good Return During Job: YES Cement Type: Class "G" Neat 15.8#

Comment: 2026/04/07:  
 Plugging Operations; Cementing: Cement-surface.  
 JSA attached as photo to this report.

Workover Contractor: JMR Services, Rig #12.  
 Cement Contractor: JMR Services.  
 REVIEWED: Form 6 plugging procedures / COA. JSA.

Daily Job Rpt:  
 SAFETY/JSA MEETING, SWC/SYLA, LOCK/OUT TAG OUT, START EQUIPMENT,  
 CHECK  
 GROUNDING, REVIEW WELL CONTROL ISSUES AND MITIGATIONS PHASE3 RA  
 (WSEA 2-A BTLK)  
 CHECK PSI, CSG 0 PSI, SURFACE 0 PSI  
 CONDITION HOLE W/70 BBLS, FLOW CHECK 5 MIN NO FLOW  
 TEST PUMP LINES, PUMP SURFACE PLUG AS FOLLOWS, 10 BBLS CHEM WASH,  
 277 SACS OR  
 56.7 BBLS OF 15.8# G-NEAT CMT @1.15 YIELD, CMT IN RETURNS @SURFACE,  
 EST CMT 795 TO  
 SURFACE  
 ND 7 1/16 5K BOP W/2 3/8 PIPE & BLIND RAMS , NU 5K WH  
 PERFORM BUBBLE/FLOW CHECK AS PER SOP FOR 30 MIN, CSG HAD NO  
 BUBBLES/FLOW,  
 SURFACE HAD NO BUBBLES/FLOW (WSEA 10-E BTLK SURFACE CMT BUBBLE  
 CHECK),TOP OFF  
 CMT, SWI  
 RIG DOWN, CLEAN RETURN TANK, PU ALL EQUIPMENT, MRO, FINAL REPORT.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Workover**

Comment:

2026/04/07:  
Plugging Operations; Cementing: Cement-surface.  
JSA attached as photo to this report.

Workover Contractor: JMR Services, Rig #12.  
Cement Contractor: JMR Services.  
REVIEWED: Form 6 plugging procedures / COA. JSA.

Reference:  
Form 6N on file. Notice of Intent to Abandon date: 12/23/2025. Approved.  
Form 42 on file. Notice of MIRU. Start Date: 03/30/2026. Approved.  
Form 42 on file. Notice of Plugging Operations. Start Date: 03/30/2026. Approved.  
Form 17 Brhd test on file. Date: 04/01/2026.  
Annual Brhd test on file. Date: 04/25/2025.  
Form 27 on file. Date: 01/26/2026. Approved.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>Comment 1:</b>                      This is a <b>PLUGGED &amp; ABANDONED WELL / WORKOVER / CEMENTING</b> audit.                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Plugging Operations: Cementing; Cement-surface.                      Battery: Abandoned.                      Abandoned Battery SE corner GPS coordinates: 40.542939 / -104.489611                      Well GPS coordinates: 40.542888 / -104.500382</p>	evinsb	04/09/2026
<p><b>Comment 2:</b>                      CECMC Audit Report Synopsis:</p> <p>On TUE 04/07/2026 at approximately 09:15 hrs. I, Bret Evins, conducted an onsite audit at:                      Operator Name: NOBLE ENERGY INC                      Location Name: AURORA USX AB/25-11P                      Location ID: 413776                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Plugging Operations: Cementing; Cement-surface.                      Battery: Abandoned.                      Abandoned Battery SE corner GPS coordinates: 40.542939 / -104.489611                      Well GPS coordinates: 40.542888 / -104.500382</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/09/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700620	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510263">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510263</a>