

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2026

Submitted Date:

04/09/2026

Document Number:

708908882

FIELD INSPECTION FORM

Loc ID 335131 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 24 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269125	WELL	PR	09/01/2004	GW	045-09323	PUCKETT 33C-25	PR
293505	WELL	PR	03/01/2023	GW	045-15016	PUCKETT 33C2-25D	PR
293506	WELL	PR	12/31/2008	GW	045-15017	PUCKETT 33B-25D	PR
293507	WELL	PR	12/31/2008	GW	045-15018	PUCKETT 33A-25D	PR
293508	WELL	PR	12/31/2008	GW	045-15019	PUCKETT 33D-25D	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Sign near entrance to location		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type BATTERY		
Comment:	Battery lacks required signage		
Corrective Action:	Comply with CECMC Rule 605		Date: 01/24/2026

Emergency Contact Number:			
	Comment: 911/970-285-2615		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:

Type	SEPARATOR		
Comment:	Barbed wire fence		
Corrective Action:			Date:
Type	OTHER		
Comment:	Liquid nitrogen tank - pipe rail fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:	No form of pressure monitoring equipment located on bradenheads		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent			
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	269125	Type:	WELL	API Number:	045-09323	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293505	Type:	WELL	API Number:	045-15016	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293506	Type:	WELL	API Number:	045-15017	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293507	Type:	WELL	API Number:	045-15018	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293508	Type:	WELL	API Number:	045-15019	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in most areas
		Sediment Traps				
		Rip Rap				
		Compaction				Light compaction in some sections
		Culverts				
		Ditches				
Berms						
		Check Dams				
		Drains				
		Gravel				Sparse to none
Compaction						Small amount of light compaction
		Berms				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 04/06/2026 at approximately 14:04 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at QB ENERGY OPERATING LLC PUCKETT 33C-25 (MESA 18) Pad Location # 335131 in Garfield County Colorado. Please refer to inspection/audit 708908094 conducted on 12/22/2025, 3 of 4 previous corrective actions have been completed. Location is within High Priority/Density/Black Bear Habitat areas. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Signs/Marker - Battery lacks required signage - Comply with Rule 605 with a CA date of 01/24/2026</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p>	smelserw	04/09/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908883	Inspection/Audit 708908882 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510452

708908884	Inspection/Audit 708908882 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510453
-----------	---	---