

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

04/09/2026

Document Number:

719700621

**FIELD INSPECTION FORM**

Loc ID 302509 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299099	WELL	TA	04/01/2020	GW	123-29254	BASHOR STATE AA 16-02	TA

**General Comment:**

\*This is an audit of the scout card and related documents followed by an AMA. (Alternate Method Audit).

<b>Location</b>			
<b>Lease Road:</b>			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type WELLHEAD		
	Comment: Yellow LTSI tag posted.		
Corrective Action:			Date:
Emergency Contact Number:			
	Comment: Posted.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	<p>*Prior audit:  CORRECTIVE ACTION ITEM(s):  During this inspection the following possible compliance issue(s) were observed:  1.) Undesirable vegetation at wellsite(s). (Weeds).  Refer to Rule 606.c for guidance.  *Remove, manage, &amp; control undesirable vegetation around wellsite(s).  Comply with Rule 606.c. (14 days). CA date: 04/17/2026.  **This audit:  *FIR Resolution Form   FIRR doc. #404609566 asserts:  Undesirable vegetation at wellsite(s). (Weeds). Has been mitigated as of 04/06/2026.  Operator provided photo(s) for verification. See photo(s) #1-4.</p>		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
	Comment: _____		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
	Type WELLHEAD		
	Comment: Iron panel.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 299099 Type: WELL API Number: 123-29254 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Battery Abandoned.  
Locked-Out, Tagged-Out | LOTO.  
Yellow LTSI tag posted at well.  
ECMC records last prod: 06/2016.  
  
Form 4 on file. TA date: 01/29/2019. Approved.  
Form 6A on file. Out-of-Svc Designation. Approved.  
Date ceased prod: 01/01/2015.

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 06/05/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p><b>Comment 1:</b>                      This is a WELL audit. Alternate Method Audit   AMA.                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Abandoned. ALL equipment has been removed.                      Abandoned Battery SE corner GPS coordinates: 40.486284 / -104.432985</p> <p>Abandoned Centralized Battery formerly served 8 Location IDs (302510, 302509, 302511, 302512, 302513, 302517, 302521, 302540).                      (Well(s): 5: Temporarily Abandoned   TA; 3: Plugged &amp; Abandoned   PA).</p> <p>*Follow-up to Field Audit Report doc. #719700555 dated 03/30/2026.                      *Follow-up to FIR Resolution Form (FIRR) doc. #404609566 dated 04/06/2026.</p>	evinsb	04/09/2026
<p><b>Comment 2:</b>                      CECMC Audit Report Synopsis:</p> <p>On THU 04/09/2026 at approximately 13:30 hrs. I, Bret Evins, conducted an AMA: Alternate Method Audit at:                      Operator Name: NOBLE ENERGY INC                      Location Name: BASHOR STATE AA-66N63W/16NWNE                      Location ID: 302509                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this report.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, dry.</p> <p>Audit observations:                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Abandoned. ALL equipment has been removed.                      Abandoned Battery SE corner GPS coordinates: 40.486284 / -104.432985</p> <p>* While conducting this audit, the following prior possible compliance issues appear to be addressed:                      *CORRECTIVE ACTION Item(s) RESOLUTION Comment:                      Refer to pg 2, "Good Housekeeping" section of this report.</p> <p>*FIR Resolution Form   FIRR doc. #404609566 asserts:                      Undesirable vegetation at wellsite(s). (Weeds). Has been mitigated as of 04/06/2026.                      Operator provided photo for verification. See photo(s) #1-4.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	04/09/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700622	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510472</a>