

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2026

Submitted Date:

04/03/2026

Document Number:

716900070

FIELD INSPECTION FORM

Loc ID: 319990 Inspector Name: Huck, Keith On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 10694
 Name of Operator: PROVIDENCE OPERATING LLC DBA POCO
 Address: 16400 DALLAS PARKWAY SUITE 400
 City: DALLAS State: TX Zip: 75428

Findings:
 7 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Erin Matthews	720-638-7545	erinm@dunamis-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202148	WELL	PR	03/01/2022	GW	001-07553	STATE OF COLORADO AN 1	PR

General Comment:
 This is a field audit of the scout card, related documents and the location. No Equipment changes since last inspection.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil below master valve. See attached photos		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 04/30/2026

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202148 Type: WELL API Number: 001-07553 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary On (3/31/2026) at approximately (2:00pm). I, Inspector Keith Huck, conducted an on-site inspection. Operator: Dunamis Energy Location name: State of Colorado AN#1 API # 001-07553 Location ID #: 319990 County: Adams While there, I observed a (PR) well. During this inspection the following possible compliance issues were observed: Stained soil below the master valve on the wellhead. Control and contain spills/releases and clean up per Rule 912.a. See attached photos A follow-up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection report.</p>	huckk	04/03/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404607880	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504863
716900071	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504859