

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

04/10/2026

Document Number:

719501024

FIELD INSPECTION FORM

Loc ID 312389 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 29470
Name of Operator: FEES JR AND SON OIL & GAS* WALTER S
Address: 2516 FORESIGHT CIRCLE RM #10
City: GRAND JUNCTION State: CO Zip: 81505

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
DePaolo, Corey		corey.depaolo@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Woodruff, Chad		cwoodruff@blm.gov	
Fees, Walter		fwalter8@bresnan.net	
Hobbs, Don		dhobbs@blm.gov	
Wilson, Justin		jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221456	WELL	PR	09/01/2025	GW	077-08057	BAR-X 32-1	SI

General Comment:

This is a field audit of the location, scout card, and related documents.

On 4/9/2026 at approximately 13:35, Compliance Inspector Matthew Morris conducted an on-site audit at FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE at Location ID #312389 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign posted.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No tank labels posted on plastic AST.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds present in secondary containment for plastic AST and across location.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	Stored supplies near separator.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Unmarked deadman on location.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PLASTIC AST		,
Comment:	Missing tank cover on AST poses a wildlife entry hazard.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	Not posted
Other (Capacity)	Not posted
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Weeds present in secondary containment.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 221456 Type: WELL API Number: 077-08057 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced January 2026 per production report. Last Production Casing test performed March 2022.

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Gravel						
		Other				
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
BAR-X 32-1 production valves are open at the wellhead. Production line is closed upstream of the separator.	morris	04/10/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719501025	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511422