

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

04/12/2026

Document Number:

708908904

FIELD INSPECTION FORM

Loc ID: 311638 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

45 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Longworth, Mike		mike.longworth@state.co.us	
QB ENERGY		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282774	WELL	PR	12/01/2009	GW	045-11838	N. PARACHUTE MF07C-4 CO4 696	PR
282776	WELL	PR	04/27/2007	GW	045-11836	N.PARACHUTE MF 13D CO4 696	PR
282777	WELL	PR	04/12/2007	GW	045-11835	N. PARACHUTE MF04D CO4 696	PR
282778	WELL	PR	01/23/2006	GW	045-11834	N.PARACHUTE MF02C CO4 696	PR
282779	WELL	PR	01/23/2006	GW	045-11833	N.PARACHUTE MF08C CO4 696	PR
282780	WELL	PR	01/23/2006	GW	045-11832	N.PARACHUTE MF03A CO4 696	PR
282781	WELL	PR	11/30/2009	GW	045-11831	N. PARACHUTE MF06C-4 CO4 696	PR
282784	WELL	PR	01/23/2006	GW	045-11829	N.PARACHUTE MF08A CO4 696	PR
282785	WELL	PR	01/23/2006	GW	045-11828	N.PARACHUTE MF01C CO4 696	PR
282786	WELL	PR	07/24/2009	GW	045-11827	N. PARACHUTE MF07A-4 CO4 696	PR
284640	WELL	PR	12/01/2009	GW	045-12249	N. PARACHUTE MF06B-4 CO4 696	PR
295477	WELL	PR	03/01/2010	GW	045-15766	N. PARACHUTE MF01C-4 CO4 696	PR
295478	WELL	PR	07/14/2011	GW	045-15767	N. PARACHUTE MF13D-31 CO4 69	PR
295479	WELL	PR	02/20/2010	GW	045-15768	N. PARACHUTE MF04B-3 CO4 696	PR

295480	WELL	PR	02/15/2010	GW	045-15769	N. PARACHUTE MF03C-4 CO4 696	PR
295481	WELL	PR	01/14/2010	GW	045-15770	N. PARACHUTE MF02C-4 CO4 696	PR
295482	WELL	PR	02/10/2010	GW	045-15771	N. PARACHUTE MF06A-4 CO4 696	PR
295483	WELL	PR	02/22/2010	GW	045-15772	N. PARACHUTE MF02B-4 CO4 696	PR
295487	WELL	PR	01/13/2010	GW	045-15777	N. PARACHUTE MF13C-31 CO4 69	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Blowdown tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign on lease road		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Staining near meter house - Please refer to photo log		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Jersey barriers		
Corrective Action:			Date:

Type	OTHER		
Comment:	Meter houses - jersey barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks & thermogens - jersey barriers		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 19		
Comment:	Sales		
Corrective Action:		Date:	
Type: Plunger Lift	# 19		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 9		
Comment:	Catalytic heaters in meter houses		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Thermogens		
Corrective Action:		Date:	
Type: Bradenhead	# 19		
Comment:	Taylor plugs located on bradenheads		
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Mechanical Condition - Large amount of external corrosion visible on ball valve (N. PARACHUTE MF07C-4 C04 696 flowline)		
Corrective Action:	Comply with CECMC Rule 608	Date:	04/19/2026
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:	Blowdown tank Tank not equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity) 120 bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Damage to secondary containment - Please refer to photo log			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	282774	Type:	WELL	API Number: 045-11838	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger & gas lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	282776	Type:	WELL	API Number: 045-11836	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger & gas lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	282777	Type:	WELL	API Number: 045-11835	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger & gas lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	282778	Type:	WELL	API Number: 045-11834	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger & gas lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	282779	Type:	WELL	API Number: 045-11833	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger & gas lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	282780	Type:	WELL	API Number: 045-11832	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger & gas lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	282781	Type:	WELL	API Number: 045-11831	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger & gas lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	282784	Type:	WELL	API Number: 045-11829	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger & gas lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						

Producing Well			
Comment:	Producing, well on plunger & gas lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	282785	Type:	WELL	API Number:	045-11828	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger & gas lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	282786	Type:	WELL	API Number:	045-11827	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger & gas lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	284640	Type:	WELL	API Number:	045-12249	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger & gas lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295477	Type:	WELL	API Number:	045-15766	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger & gas lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295478	Type:	WELL	API Number:	045-15767	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger & gas lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295479	Type:	WELL	API Number:	045-15768	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger & gas lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295480	Type:	WELL	API Number:	045-15769	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger & gas lift		

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295481	Type:	WELL	API Number:	045-15770	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger & gas lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295482	Type:	WELL	API Number:	045-15771	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger & gas lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295483	Type:	WELL	API Number:	045-15772	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger & gas lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295487	Type:	WELL	API Number:	045-15777	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger & gas lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Small amount of light compaction
		Ditches				
		Gravel				Sparse to none in sections
Compaction						Small amount of light compaction
Ditches						
Gravel						Sparse
				Material Handling And Spill Prevention		Chemical tank containments
		Culverts				
Retention Ponds						

Comment: Chemical tank containments approximately 3/8 full of fluid/BMP's may need maintenance in the near future.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 04/09/2026 at approximately 11:22 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at QB ENERGY OPERATING LLC N. PARACHUTE MF07C-4 C04 696 Pad Location # 311638 in Garfield County Colorado. Please refer to inspection/audit 707800703 conducted on 02/05/2024 & inspection/audit 708303056 conducted on 11/12/2024, previous corrective actions have been completed. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is within Rule 411b Generalized Intermediate Buffer. Location is approximately 191 yards from Parachute Creek. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Equipment - Mechanical Condition - Large amount of external corrosion visible on ball valve - Comply with Rule 608 with a CA date of 04/19/2026</p> <p>Comments -</p> <p>Housekeeping - Staining near meter house</p> <p>Tanks & Berms - Damage to secondary containment</p> <p>Stormwater - Chemical tank containments approximately 3/8 full of fluid/BMP's may need maintenance in the near future.</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p> <p>Any corrective actions from previous inspections/audits that have not been addressed are still applicable.</p>	smelserw	04/12/2026

Attached Documents

You can go to ECOM Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908905	Inspection/Audit 708908904 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511909
708908906	Inspection/Audit 708908904 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511910