

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2026

Submitted Date:

04/06/2026

Document Number:

719201009

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312930 _____ Gaasche, Emily _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10524
Name of Operator: GRMR OIL & GAS LLC
Address: 1324 WEST VILLARD STREET
City: DICKINSON State: ND Zip: 58601

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Adesoye, Yosoye	404-723-6547	yosoye@grmroilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222880	WELL	PA	05/29/2014	OW	081-06240	BEAVER-DURHAM 12-32	RI
312930	LOCATION	CL			-	BEAVER-DURHAM-65N90W 32NWSW	RI

General Comment:

On 03/25/2026, NW Reclamation Specialist Emily Gaasche conducted a final reclamation inspection at GRMR Oil & Gas LLC's BEAVER-DURHAM-65N90W/32NWSW location in Moffat County, Colorado.

The location is within CPW High Priority Habitat: Elk Migration Corridor, Elk Production Area, Elk Severe Winter Range, Elk Winter Concentration Area, Mule Deer Migration Corridor, Mule Deer Severe Winter Range.

The following compliance issues were observed during this inspection:
-Noxious weeds

Refer to the Reclamation and Stormwater sections of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Inspected Facilities

Facility ID: 222880 Type: WELL API Number: 081-06240 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 312930 Type: LOCATION API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Pass

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation Pass Dust and erosion control _____

Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present Pass Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text" value="No stormwater issues observed during this inspection."/>						Date: _____
Corrective Action: <input type="text"/>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
<p>Reclamation Comments: Form 4 #402440142 stating Final Reclamation Completed received on 07/09/2020.</p> <p>Vegetation at the location has established well, and areas of non-uniformity noted in inspection #702801541 appear to have filled in. Vegetation is primarily composed of smooth brome, slender wheatgrass, crested wheatgrass and orchardgrass with secondary amounts of big sagebrush and curlycup gumweed. Tertiary amounts of rubber rabbitbrush, common yarrow and Indian ricegrass are present. A small patch of Canada thistle, a List B noxious weed, is present on the northern end of the location and basal rosettes were observed in tertiary amounts, indicating reproduction. Weed management is required pursuant to Rule 1004.e.; inspector recommends immediate attention to prevent the infestation from spreading.</p> <p>No other issues were noted; all surface equipment has been removed, no trash/debris observed. A follow-up inspection will be conducted during the 2026 growing season to assess weed control efforts at the location before the location receives a passing final reclamation inspection.</p> <p>Well API #05-081-06240 was plugged and abandoned on 5/29/2014 and received facility closure via Form 6S #400630456.</p>	gaaschee	04/06/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404609164	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7505785
404609215	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7505818
719201010	Inspection Photos	03252026 BEAVER-DURHAM-65N90W 32NWSW Inspection Photos.pdf