

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2026

Submitted Date:

04/06/2026

Document Number:

721100294

FIELD INSPECTION FORM

Loc ID 306776 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Findings:

- 20 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Blair, Jamie		jamie.blair@state.co.us	
Walker, Kyle		kwalter@enduringresources.com	All SW field inspections
Huntington, Heather		hhuntington@enduringresources.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264201	WELL	PR	07/11/2002	CBM	067-08736	KOSHAK B-4A	PR

General Comment:

On Friday, April 3, 2026, at 4:30 PM, southwest compliance specialist Jamie Blair performed a producing well compliance audit and inspection. Corrective actions were identified. Photos are linked in the attachments section of this report.

Location			
Lease Road:			
Type	Access		
comment:	Seasonal rutting after recent rain storm.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Near meter run by pad entrance. Photo 1.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergence 1-800-916-7897 or 911.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	dead vegetative debris accumulating on northeast corner of pad piled against fence. Photo 3.		
Corrective Action:			Date:
Type	STORAGE OF SUPL		
Comment:	Unused chainlink gate on west edge of fence. Photo 15.		
Corrective Action:	Remove or return to service to comply with 606.		Date: 05/04/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	8 foot barbed wire topped chain link perimeter fence. Gate open at time of inspection.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	2 chemical injection system, each container on secondary contianment.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	1/15/26 calibration date.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	wellhead		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric drive with well gas generator.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	2" steel on west side of pad near meter run.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Solar telemetry		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		27.208806,-107.850565
Comment:	Has expanded metal wildlife protection grate on top.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 264201 Type: WELL API Number: 067-08736 Status: PR Insp. Status: PR

Producing Well

Comment: PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/22/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass					

Comment: Seasonal rutting on road, and deep ruts on well pad along with 25'x25' est. puddle by gate after recent rainstorm event.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Corrective action excess equipment. See links to photos in attachment section.	blairj1	04/03/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404609219	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7505820
721100296	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7505817