

Inspection Photos

API: 009-06440

Operator: MURFIN DRILLING COMPANY

Inspection Date: 4/9/2026

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the beginning of the access road.



Inspection Photos



Photo 2. Facing west about 140 feet from the wellsite. This area appear to be where flowline risers were removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06440 | Date: 4/9/2026

Inspection Photos



Photo 3. Facing west toward the location.



Inspection Photos



Photo 4. Near the abandoned well is a capped flowline. There is standing water at this area from a possible leak of the flowline.



Inspection Photos



Photo 5. Facing toward the cut and capped well. There appears to be wet impacted soils around the abandoned well.



Inspection Photos



Photo 6. Facing west toward the excavated abandoned well site.

