

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2026

Submitted Date:

04/07/2026

Document Number:

697012632

FIELD INSPECTION FORM

Loc ID 449884 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 22 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449881	WELL	PR	07/01/2023	OW	123-44563	NEWBY STATE 30N-34HZ	PR
449882	WELL	PR	05/01/2024	OW	123-44564	NEWBY 1N-33HZ	PR
449883	WELL	PR	05/01/2022	OW	123-44565	NEWBY STATE 26N-33HZ	PR
449885	WELL	PR	06/01/2020	OW	123-44566	NEWBY 27N-33HZ	PR
449886	WELL	PR	07/01/2023	OW	123-44567	NEWBY 28N-33HZ	PR
449887	WELL	PR	11/01/2024	OW	123-44568	NEWBY 2N-33HZ	PR
451358	WELL	PR	03/01/2025	OW	123-45087	NEWBY STATE 37N-4HZ	PR
451359	WELL	PR	10/21/2018	OW	123-45088	NEWBY STATE 16N-4HZ	PR
451360	WELL	PR	04/01/2020	OW	123-45089	NEWBY STATE 15N-4HZ	PR
451361	WELL	PR	10/13/2018	OW	123-45090	NEWBY STATE 34N-3HZ	PR
451362	WELL	PR	04/01/2022	OW	123-45091	NEWBY STATE 36N-4HZ	PR
451363	WELL	PR	10/13/2018	OW	123-45092	NEWBY STATE 38N-4HZ	PR

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	x 12		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical systems		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Pumping unit weight at west edge of the location and fencing panel next to chemical system, see attached photos.		
Corrective Action:	Comply with Rule 606.		Date: <u>05/08/2026</u>
Type	TRASH		
Comment:	Miscellaneous trash around the location, see attached photos.		
Corrective Action:	Comply with Rule 606.		Date: <u>05/08/2026</u>

Overall Good:

Spills:

Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:

Equipment:

Type				corrective date
Type: Flow Line	# 12			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	#			
Comment:	Automation array, electrical systems, chemical systems in secondary containment.			
Corrective Action:				Date:
Type: Plunger Lift	# 12			
Comment:				
Corrective Action:				Date:

Type: Bradenhead	# 12	
Comment:	Bradenhead valves are exposed at surface.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Tank battery #481094				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	449881	Type:	WELL	API Number:	123-44563	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	449882	Type:	WELL	API Number:	123-44564	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	449883	Type:	WELL	API Number:	123-44565	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	449885	Type:	WELL	API Number:	123-44566	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	449886	Type:	WELL	API Number:	123-44567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	449887	Type:	WELL	API Number:	123-44568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	451358	Type:	WELL	API Number:	123-45087	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	451359	Type:	WELL	API Number:	123-45088	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451360 Type: WELL API Number: 123-45089 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451361 Type: WELL API Number: 123-45090 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451362 Type: WELL API Number: 123-45091 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451363 Type: WELL API Number: 123-45092 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary On Tuesday 4/7/2026 at approximately 12:05 hours I, Inspector Tom Peterson, conducted an on-site inspection at the KMG Newby 27N-33HZ Pad location #449884 in Weld County, Colorado. While there, I observed unused equipment and trash on the location. During this inspection the following possible compliance issues were observed: Rule 606.with a corrective action date of 5/8/2026. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	petersont	04/07/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404611109	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7507230
697012633	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7507225