

Inspection Photos

API: 009-06637

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 4/9/2026

County: BACA



Inspection Photos



Photo 1. Facing west toward the location. This area of the location is revegetating very well.



Inspection Photos



Photo 2. Center of the location facing south.



Inspection Photos



Photo 3. Facing toward the northwest side of the location. This area is slowly revegetating but could benefit from additional reseeding.



Inspection Photos



Photo 4. Drone aerial photo facing south toward the location.



Inspection Photos



Photo 5. Drone aerial photo facing southeast at the location. This area is slowly revegetating but could benefit from additional reseeding.



Inspection Photos




Photo 5. Drone aerial photo facing east at the location.

