

Inspection Photos

API: 009-06668

Operator: JETTA OPERATING COMPANY INC

Inspection Date: 4/9/2026

County: BACA



Inspection Photos



Photo 1. Facing south toward the former access road. The native vegetation has re-established along the road.



Inspection Photos



Photo 2. Facing south toward the location. The native vegetation has re-established throughout the location.



Inspection Photos



Photo 3. Center of the location facing south.



Inspection Photos



Photo 4. Center of the location facing east.



Inspection Photos



Photo 5. Center of the location facing north.



Inspection Photos



Photo 6. Center of the location facing west.



Inspection Photos



Photo 7. Facing north toward the surrounding reference area which consists of native Sand dropseed, Sand sage, Prairie sandreed, ect.



Inspection Photos



Photo 8. Drone aerial photo facing south along the former access road.



Inspection Photos



Photo 9. Drone aerial photo facing south toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06668 | Date: 4/9/2026

Inspection Photos



Photo 10. Drone aerial photo facing north toward the location.

