

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2026

Submitted Date:

04/14/2026

Document Number:

717300896

FIELD INSPECTION FORM

Loc ID 488780 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248222	WELL	PA		GW	123-16020	BARCLAY 2-16K	PA
271925	WELL	PA		GW	123-22143	BARCLAY FARMS L 02-16JI	PA
414615	WELL	PA		GW	123-30796	BARCLAY FARMS L 11-27D	PA
488781	TANK BATTERY	AC	12/19/2024		-	BRCLY 2-16K, BRCLY FMS L 2-16JI TB 499781	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 248222 Type: WELL API Number: 123-16020 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 271925 Type: WELL API Number: 123-22143 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 414615 Type: WELL API Number: 123-30796 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 488781 Type: TANK API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

ECMC Comments

Comment	User	Date
As outlined on ECMC form 19 spill report Doc #404496253 received on 01/08/2026: While conducting wellhead plugging and abandonment and flowline removal activities at the Barclay Farms L 2-15 JI wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. The wellhead has been plugged and abandoned.	maclarej	04/14/2026
Wells (3) are plugged and abandoned; ECMC form 42 notice of start of plugging operations received Nov 2024. Off location flowline AIP/ removal appears to be completed. ECMC form 42 notice of flowline abandonment completed doc #404072633 received on 01/28/2025. No flowlines/ risers observed at PA well or facility/ battery areas. Open excavations observed at PA wells and facility/ battery areas. Remediation work in progress.	maclarej	04/14/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300912	Excavations at facility/ battery; signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7513819
717300913	Fenced excavation at PA well; 2-16K	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7513820