

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2026

Submitted Date:

04/08/2026

Document Number:

716302146

FIELD INSPECTION FORM

Loc ID 322277 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
12 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 17210
 Name of Operator: CINNAMON CREEK OIL & GAS INC
 Address: P O BOX 544
 City: WALSH State: CO Zip: 81090

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mills, Hellen		heleningle1221@yahoo.com	All Inspections
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210100	WELL	PR	09/01/2020	OW	043-40037	YANKOVICK 1	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	PHOTO 5: WEEDS/VEGETATION NOT MAINTAINED THROUGHOUT LOCATION.		
Corrective Action:	MAINTAIN WEEDS/ VEGETATION, COMPLY WITH RULE 606.	Date:	04/25/2026

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 1	ELECTRICAL METER AND BREAKER			
Pump Jack	# 1	ELECTRIC DRIVE			
Bradenhead	# 0	PHOTO 7: Bradenhead inaccessible or not visible (NO BRHD INSTALLED ON WELLHEAD). Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) Please provide documentation as to how operator is going to move forward. THIS IS A FOLLOW-UP TO INSPS 707901272, 713600409 AND 695108710. IMMEDIATE ACTION IS REQUIRED. OPERATOR HAS STATED IN FIRR DOC #403676133 THEY ARE SEEKING A VARIANCE FROM FURTHER TESTING. ATTACHED IS THE REQUEST FOR A VARIANCE PROVIDED TO THE COMPLIANCE SPECIALIST BY OPERATOR.	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) Please provide documentation as to how operator is going to move forward. THIS IS A FOLLOW-UP TO INSPS 707901272, 713600409 AND 695108710. IMMEDIATE ACTION IS REQUIRED.		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		FIBERGLASS AST		38.426207,-105.209944
Comment:	PHOTO 6: CAPACITY IS NOT POSTED AT CRUDE OIL TANK BATTERY.				
Corrective Action:	POST TANK CAPACITY AT TANK BATTERY, COMPLY WITH RULE 605. THIS IS A FOLLOW-UP TO INSP'S 695108710 AND 687903596 IMMEDIATE ACTION IS REQUIRED.				Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210100 Type: WELL API Number: 043-40037 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/21/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: A BRADENHEAD TEST WAS SUBMITTED FOR THIS WELL ON 3/21/2022 DOC #402993098. THERE IS NOBRHD INSTALLED ON WELL.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

