

Final Reclamation and Stormwater Inspection

April 13, 2026

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 463225

Well Name: Hippen UU 32-2,13; Pezoldt UU 32-4J/

Inspection Document #: 718601575

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hippen UU 32-2,13; Pezoldt
UU 32-4J/
Location ID: 463225



Photo 1. Looking east across the location from the west side. All equipment has been removed. Weeds appear to be controlled on the tank battery at the time of inspection.



Photo 2. Looking west across the west side of the tank battery from the center of the location. Desirable perennial vegetation is present on this side of the location including saltgrass and blue gramma.

Inspection Photos
Location Name: Hippen UU 32-2,13; Pezoldt
UU 32-4J/
Location ID: 463225



Photo 3. Looking east from the center of the location. Desirable perennial vegetation is present on the east side in areas that are not being driven on.



Photo 4. Looking west from the east side of the location. It appears that a portion of the tank battery is being used for parking for a nearby equipment depot.

Inspection Photos
Location Name: Hippen UU 32-2,13; Pezoldt
UU 32-4J/
Location ID: 463225



Photo 5. Cars are parking in this area because of this equipment/ materials depot nearby.



Photo 6. Reference vegetation to the west of the tank battery location. Vegetation is primarily smooth brome.