

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/15/2026

Submitted Date:

04/15/2026

Document Number:

717300915

FIELD INSPECTION FORM

Loc ID 321459 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272632	WELL	SI	11/01/2025	GW	013-06509	VICKLUND G 32-2	PA
336072	LOCATION	AC			-	VICKLUND-61N69W 2NWNE	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 272632 Type: WELL API Number: 013-06509 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 336072 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Vicklund 32-2); ECMC form 42 notice of start of plugging operations doc #404509095 received on 01/16/2026. The facility/ tank battery is decommissioned; tanks, equipment and flowline removal work has been completed. No flowlines/ risers observed at PA well area. Remediation work is in progress.	maclarej	04/15/2026
Civitas contractors on location have finished facility decommissioning and flowline removal work; since previous inspection 3/26.		
As outlined on ECMC form 19 spill report Doc #404588595 received on 03/20/2026: During decommissioning historical impacts were discovered.	maclarej	04/15/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300921	Signage at PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515689
717300922	Facility decommissioned; flowlines removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515690