

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2026

Submitted Date:

04/09/2026

Document Number:

701104666

**FIELD INSPECTION FORM**

Loc ID: 322298 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10550  
Name of Operator: MUSTANG RESOURCES LLC  
Address: 3 GREENWAY PLAZA STE 1360  
City: HOUSTON State: TX Zip: 77046

**Findings:**

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Melissa Layman		mlayman@venatorresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210183	WELL	PR	09/01/2024	GW	045-05078	JUHAN FEDERAL 1-35-6S-94W	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
 Tank loadline not bullplugged. Plug is laying by line.  
 Comply with Rule 603.i..  
 4/13/2026  
 No smoking sign is knocked over in tank berm.  
 Install sign to comply with Rule 605.g. and 610.f.  
 CA Date 5/9/2026  
 Pressure relief valve on top of production tank is not in working order. The lid is flipped over backwards.  
 Comply with Rule Rule 608.a.(9) and 608.a.(10).C..  
 CA Date 5/9/2026  
 Liner inside of tank battery berm is damaged.  
 Repair or replace berm liner. Rule 603.o.  
 CA Date 5/9/2026  
 Unused flowline riser at separator missing OOSLAT tag.  
 Comply with Rule 1101.a.(3).C.. Install an OOSLAT tag to unused riser.  
 CA Date 5/9/2026

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	No smoking sign is knocked over in tank berm.		
Corrective Action:	Install sign to comply with Rule 605.g. and 610.f.	Date:	05/09/2026

**Emergency Contact Number:**

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	Unused flowline riser at separator missing OOSLAT tag.		
Corrective Action:	Comply with Rule 1101.a.(3).C.. Install an OOSLAT tag to unused riser.		Date: 05/09/2026
Type: Emission Control Device	# 1		
Comment:	Pressure relief valve on top of production tank is not in working order. The lid is flipped over backwards.		
Corrective Action:	Comply with Rule Rule 608.a.(9) and 608.a.(10).C..		Date: 05/09/2026

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		

Comment:	Tank loadline not bullplugged. Plug is laying by line.	Date:	04/13/2026
Corrective Action:	Cmply with Rule 603.i..		

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth			Base Insufficient	Inadequate
Comment:	Liner inside of tank battery berm is damaged.			
Corrective Action:	Repair or replace berm liner. Rule 603.o.			Date: 05/09/2026

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 210183 Type: WELL API Number: 045-05078 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404613717	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7509463">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7509463</a>
701104668	Flowline integrity inspection 701104666 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7509462">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7509462</a>