

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2026

Submitted Date:

04/09/2026

Document Number:

701104669

FIELD INSPECTION FORM

Loc ID 431089 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	
		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431090	WELL	PR	03/01/2014	GW	045-21843	Savage RWF 11-35	EG
431091	WELL	PR	03/01/2014	GW	045-21844	Savage RWF 311-35	EG
431092	WELL	PR	12/30/2013	GW	045-21845	Savage RWF 421-35	EG
431093	WELL	PR	12/30/2013	GW	045-21846	Savage RWF 321-35	EG
431094	WELL	PR	03/01/2014	GW	045-21847	Savage RWF 411-35	EG
431095	WELL	PR	12/30/2013	GW	045-21848	Savage RWF 21-35	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
No plugs in glycol vessel valves on the dual separator unit.
Comply with Rule 1002.f(2).B..
CA Date 04/17/2026
Vegetation growing out from under Produced water tank.
Remove vegetation, inspect liner for integrity. Comply with Rule 603.o.
CA Date 05/09/2026

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Horizontal Heated Separator	# 6		corrective date
Comment:	No plugs in glycol vessel valves on the dual separator unit.		
Corrective Action:	Comply with Rule 1002.f(2).B..	Date:	04/17/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient		Inadequate	
Comment: Vegetation growing out from under Produced water tank.					
Corrective Action: Remove vegetation, inspect liner for integrity. Comply with Rule 603.o.					Date: 05/09/2026

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 431090 Type: WELL API Number: 045-21843 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431091 Type: WELL API Number: 045-21844 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431092 Type: WELL API Number: 045-21845 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431093 Type: WELL API Number: 045-21846 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431094 Type: WELL API Number: 045-21847 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431095 Type: WELL API Number: 045-21848 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404614610	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510188
701104670	Flowline integrity inspection 701104669 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510187