

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2026

Submitted Date:

04/09/2026

Document Number:

701104671

FIELD INSPECTION FORM

Loc ID: 322314 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10550
Name of Operator: MUSTANG RESOURCES LLC
Address: 3 GREENWAY PLAZA STE 1360
City: HOUSTON State: TX Zip: 77046

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		mark.schlagenhauf@state.co.us	
Layman, Melissa	(661) 444-2361	mlayman@venatorresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210256	WELL	PR	07/01/2024	GW	045-06012	RULISON FEDERAL 35-94-6S-94W	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
No smoking sign is hanging by one wire.
Install sign to comply with Rule 605.g. and 610.f.
CA Date 5/9/2026
Meter shed paint is deteriorated.
Comply with Rule 425.a.(1)
CA Date 6/30/2026

Location			
Lease Road:			
Type			
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	No smoking sign is hanging by one wire.		
Corrective Action:	Install sign to comply with Rule 605.g. and 610.f.		Date: 05/09/2026
Emergency Contact Number:			
Comment:	911		Date:
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Gas Meter Run	# 1	corrective date
Comment:	Meter shed paint is deteriorated.		
Corrective Action:	Comply with Rule 425.a.(1)		Date: 06/30/2026
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 210256 Type: WELL API Number: 045-06012 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404614612	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510189
701104672	Flowline integrity inspection 701104671 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510172