

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2026

Submitted Date:

04/09/2026

Document Number:

701104673

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
323901 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		mark.schlagenhauf@state.co.us	
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211129	WELL	PR	12/23/1994	GW	045-06888	SAVAGE RMV 15-35	EG
421918	WELL	PR	12/26/2012	GW	045-20449	Savage RWF 343-34	EG
421919	WELL	PR	09/13/2012	GW	045-20450	Savage RWF 312-35	EG
421920	WELL	PR	12/14/2012	GW	045-20451	Savage RWF 542-34	EG
421921	WELL	PR	09/13/2012	GW	045-20452	Savage RWF 42-34	EG
421922	WELL	PR	06/01/2024	GW	045-20453	Savage RWF 522-35	EG
421923	WELL	SI	05/01/2024	GW	045-20454	Savage RWF 323-35	EG
421924	WELL	PR	10/12/2012	GW	045-20455	Savage RWF 422-35	EG
421925	WELL	PR	09/13/2012	GW	045-20456	Savage RWF 441-34	EG
421926	WELL	PR	10/12/2012	GW	045-20457	Savage RWF 342-34	EG
421927	WELL	PR	10/12/2012	GW	045-20458	Savage RWF 442-34	EG
421928	WELL	PR	12/14/2012	GW	045-20459	Savage RWF 22-35	EG
421929	WELL	PR	09/30/2012	GW	045-20460	Savage RWF 23-35	EG
421930	WELL	PR	12/26/2012	GW	045-20461	Savage RWF 412-35	EG
421931	WELL	PR	09/13/2012	GW	045-20462	Savage RWF 12-35	EG
422119	WELL	PR	01/01/2013	GW	045-20492	Savage RWF 313-35	EG
422187	WELL	PR	12/26/2012	GW	045-20520	Savage RWF 413-35	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection

No plugs in glycol vessel valves on the dual separator unit.

Comply with Rule 1002.f(2).B..

CA Date 04/25/2026

Corrosion of valve on separator riser manifold.

Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

CA Date 04/25/2026

Flowline from back of tank battery is shut in but the pad lock is open.

Valve on the bottom the line hanging over the tank battery berm has no plug in it.

Inspect shut in flowline and apply OOSLAT

Comply with Rule 1101.a.(3).C..

CA Date 05/09/2026

No battery sign at tank battery.

Install sign to comply with Rule 605.e.

CA Date 05/09/2026

Location			
Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No battery sign at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 05/09/2026
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Horizontal Heated Separator	# 17		corrective date
Comment:	No plugs in glycol vessel valves on the several separator units.		
Corrective Action:	Comply with Rule 1002.f(2).B..		Date: 04/25/2026
Type: Flow Line	# 1		
Comment:	Flowline from back of tank battery is shut in but the pad lock is open. Valve on the bottom the line hanging over the tank battery berm has no plug in it.		
Corrective Action:	Inspect shut in flowline and apply OOSLAT Comply with Rule 1101.a.(3).C..		Date: 05/09/2026
Type: Other	# 1		
Comment:	Corrosion of valve on separator riser manifold.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 04/25/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment: Rust at bottom bolts on man hatch.						
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	211129	Type:	WELL	API Number:	045-06888	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421918	Type:	WELL	API Number:	045-20449	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421919	Type:	WELL	API Number:	045-20450	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421920	Type:	WELL	API Number:	045-20451	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421921	Type:	WELL	API Number:	045-20452	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421922	Type:	WELL	API Number:	045-20453	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421923	Type:	WELL	API Number:	045-20454	Status:	SI	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421924	Type:	WELL	API Number:	045-20455	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421925	Type:	WELL	API Number:	045-20456	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421926	Type:	WELL	API Number:	045-20457	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421927	Type:	WELL	API Number:	045-20458	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421928	Type:	WELL	API Number:	045-20459	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421929	Type:	WELL	API Number:	045-20460	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421930	Type:	WELL	API Number:	045-20461	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421931	Type:	WELL	API Number:	045-20462	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	422119	Type:	WELL	API Number:	045-20492	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Facility ID: 422187 Type: WELL API Number: 045-20520 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404614614	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510190
701104674	Flowline integrity inspection 701104673 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510186