

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404621911

Date Received:
04/16/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10840
Name of Operator: ABUNDANCE ENERGY SERVICES LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Abundance</u>		<u>aprice@abundance-energy.com</u>
<u>Blair, Jamie</u>		<u>jamie.blair@state.co.us</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Abundance</u>		<u>sjbcompliance@abundance-energy.com</u>
<u>Abundance</u>		<u>jepugh@abundance-energy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 721100301
Inspection Date: 04/07/2026 FIR Submit Date: 04/10/2026 FIR Status:

Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC Company Number: 10840
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 311895

Location Name: IGW Number: 152 County:
Qtrqtr: NWS Sec: 15 Twp: 33N Range: 9W Meridian: N
W
Latitude: 37.100910 Longitude: -107.818700

FACILITY - API Number: 05-067-00 Facility ID: 311895

Facility Name: IGW Number: 152
Qtrqtr: NWS Sec: 15 Twp: 33N Range: 9W Meridian: N
W
Latitude: 37.100910 Longitude: -107.818700

CORRECTIVE ACTIONS:

1 CA# 212208

Corrective Action: Comply with 605.h.

Date: 05/11/2026

Response: CA COMPLETED

Date of Completion: 04/13/2026

Operator Comment: The sign on the Above grade tank (that has a visible containment liner all around the tank on surface) has been updated to reflect Abundance Energy Services as the operator.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 212209

Corrective Action: Conspicuously display calibration record documenting calibration within last year to comply with rule 430.d.

Date: 05/11/2026

Response: CA COMPLETED

Date of Completion: 04/13/2026

Operator Comment: The Meter card for the IGW 106 has been updated with the current information. The last calibration performed was on 1/19/2026.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 212210

Corrective Action: Remove or return to service to comply with rule 608.d by maintaining and operating equipment in a way that prevents static charge or stray current hazards.

Date: 04/13/2026

Response: CA COMPLETED

Date of Completion: 04/13/2026

Operator Comment: The Un-used Spare wires by the IGW 106 well head have been Properly terminated and no longer have exposed copper wire.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached for remedial report.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 4/16/2026 7:08:37 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404621912	Remedial Report
-----------	-----------------

Total Attach: 1 Files