

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/16/2026

Submitted Date:

04/16/2026

Document Number:

697012676

**FIELD INSPECTION FORM**

Loc ID 332913 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
| ,            |       | Inspections@civiresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 287306      | WELL | PR     | 02/01/2025  | GW         | 123-24294 | CIRBO 6-4-5   | WK          |

**General Comment:**

This is a well plugging audit.

**Location**

Overall Good:

| <b>Signs/Marker:</b> |                      |       |  |
|----------------------|----------------------|-------|--|
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | DRILLING/RECOMP      |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

| <b>Spills:</b> |      |        |  |  |
|----------------|------|--------|--|--|
| Type           | Area | Volume |  |  |
|                |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

| <b>Fencing/:</b>   |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
| Type               | TANK BATTERY                      |       |  |
| Comment:           | <a href="#">Livestock fencing</a> |       |  |
| Corrective Action: |                                   | Date: |  |
| Type               | SEPARATOR                         |       |  |
| Comment:           | <a href="#">Livestock fencing</a> |       |  |
| Corrective Action: |                                   | Date: |  |

| <b>Equipment:</b>         |   |       | corrective date |
|---------------------------|---|-------|-----------------|
| Type: Ancillary equipment | # 1   |       |                 |
| Comment:                  | <a href="#">Automation array</a>                        |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Bradenhead          | # 1   |       |                 |
| Comment:                  | <a href="#">Bradenhead valve is exposed at surface.</a> |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Gas Meter Run       | # 1   |       |                 |

|                                   |     |  |       |
|-----------------------------------|-----|--|-------|
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Bird Protectors             | # 2 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Plunger Lift                | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Emission Control Device     | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Flow Line                   | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Horizontal Heated Separator | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |

**Tanks and Berms:**

| Contents           | #        | Capacity | Type           | Tank ID | SE GPS |
|--------------------|----------|----------|----------------|---------|--------|
| PRODUCED WATER     | 1        | OTHER    | PBV FIBERGLASS |         | ,      |
| Comment:           | 150 bbls |          |                |         |        |
| Corrective Action: |          |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |

|                    |  |
|--------------------|--|
| Other (Type) _____ |  |
|--------------------|--|

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |  |  |       |
|--------------------|--|--|--|-------|
| Yes/No             |  |  |  |       |
| Comment:           |  |  |  |       |
| Corrective Action: |  |  |  | Date: |

**Flaring:**

|                    |  |  |  |       |
|--------------------|--|--|--|-------|
| Type               |  |  |  |       |
| Comment:           |  |  |  |       |
| Corrective Action: |  |  |  | Date: |

**Inspected Facilities**

Facility ID: 287306 Type: WELL API Number: 123-24294 Status: PR Insp. Status: WK

**Workover**

Comment: Run RBL from 5300' KB to surface, RD SureFire e-line, TIH with tbg to 5265' KB, condition wellbore with rig pump.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697012677    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7517832">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7517832</a> |