

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2026

Submitted Date:

04/10/2026

Document Number:

701104677

FIELD INSPECTION FORM

Loc ID: 334789 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		mark.schlagenhauf@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211547	WELL	PR	05/01/2001	GW	045-07307	SHAEFFER 18-6	EG
259763	WELL	PR	09/20/2001	GW	045-07781	SHAEFFER 18-6B (F18)	EG
259764	WELL	PR	09/20/2001	GW	045-07782	SHAEFFER 18-6A	EG
259765	WELL	PR	08/24/2001	GW	045-07783	SHAEFFER 18-3A (F18)	EG
259773	WELL	PR	08/24/2001	GW	045-07784	SHAEFFER 18-3B (F18)	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Follow up to 02/27/2026 inspection #701104559
Old patch on top of tank has been replaced.

Dumpline fitting on top of north tank is corroded.
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.
CA Date 4/25/2026

Location

Lease Road:

Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

			corrective date
Type: Flow Line	# 1		
Comment:	Dumpline fitting on top of north tank is corroded.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 04/25/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		
Comment:	Old patch on top of tank has been replaced.				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Inadequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: <u>211547</u>	Type: <u>WELL</u>	API Number: <u>045-07307</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>259763</u>	Type: <u>WELL</u>	API Number: <u>045-07781</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>259764</u>	Type: <u>WELL</u>	API Number: <u>045-07782</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>259765</u>	Type: <u>WELL</u>	API Number: <u>045-07783</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>259773</u>	Type: <u>WELL</u>	API Number: <u>045-07784</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404615018	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510556
701104678	Flowline integrity inspection 701104677 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7510554