

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2026

Submitted Date:

04/10/2026

Document Number:

708908889

**FIELD INSPECTION FORM**

Loc ID 324373 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: 401545241

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

22 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
LARAMIE ENERGY		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285192	WELL	PR	08/07/2013	GW	045-12399	SHELL 797-14-01D	PR

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:	Tree limbs partially blocking lease road - please refer to photo log		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
	Type OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
	Type BATTERY		
Comment:			
Corrective Action:		Date:	
	Type OTHER		
Comment:	Sign near entrance to location		
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
	Comment: 911/1-800-891-6191		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type OTHER		
Comment:	Chemical tank - pipe rail fence & hog panels		
Corrective Action:		Date:	
	Type LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Pipe rail fence & hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	Pig station not listed in FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 285192 Type: WELL API Number: 045-12399 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in most areas
Ditches						
Compaction						Small amount of light compaction
		Compaction				Light compaction in some sections
		Berms				
Rip Rap						
				Material Handling And Spill Prevention	Fail	Failure to maintain chemical BMP
		Check Dams				
		Ditches				
		Culverts				
		Sediment Traps				
		Gravel				Sparse to none
		Drains				
		Retention Ponds				
		Rip Rap				
Sediment Traps						
Berms						

**Comment:** 1. Failure to maintain chemical BMP - Chemical tank containment full of fluid/BMP insufficient to contain possible spill (Additionally standing fluid on top of chemical tank containment constitutes a wildlife hazard)

At approximately 12:21 hours observed chemical tank containment full of fluid. At approximately 12:28 hours I called Chance with Laramie Energy, left him a voicemail & let him know about the chemical tank containment & that I was issuing a 24 hour corrective action on observed compliance issue. Chance texted me at approximately 12:35 hours & said he would take care it. At approximately 18:28 hours Chance texted me photos of the containment being pulled & showing that there was no fluid remaining on top of the containment.

**Corrective Action:** Comply with CECMC Rules 1002 & 602

**Date:** 04/11/2026

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 04/10/2026 at approximately 12:10 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at LARAMIE ENERGY LLC SHELL 797-14-01D Pad Location # 324373 in Garfield County Colorado.                      Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area.                      Location is approximately 329 yards from Bowdish Gulch.                      While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Stormwater - Failure to maintain chemical BMP - Comply with Rules 1002 &amp; 602 with a CA date of 04/11/2026</p> <p>Comments -</p> <p>Access - Tree limbs partially blocking lease road</p> <p>Equipment - Pig station not listed in FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p>	smelserw	04/10/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404616338	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511851">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511851</a>
404616339	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511852">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511852</a>
708908890	Inspection/Audit 708908889 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511849">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511849</a>
708908891	Inspection/Audit 708908889 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511850">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511850</a>