

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

04/10/2026

Document Number:

715204291

FIELD INSPECTION FORM

Loc ID 310907 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10730
Name of Operator: CWC PETRO LLC
Address: 6957 #A ISABELL LN
City: ARVADA State: CO Zip: 80007

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
,		dnr_cogccengineering@state.co.us	
Wolverton, Casey		casey.wolverton@state.co.us	
Beasley, Nolan		nolan.beasley@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Clark, Christopher	(303) 519-7870	cwclark@cwcpetro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296428	WELL	SI	06/01/2021	DSPW	125-11298	MILDRED SOUTH WDW 2-15	SI

General Comment:

On 4/6/26 SE Compliance Specialist Brian Welsh conducted a Routine UIC Inspection. During the inspection, the data and photos in this report were obtained for further documentation about current operations and site status

Also, on 3/20/26 at 4:36pm the area inspector reached out to the operator via email to have a Form 42, 10 day notice, submitted for the past due UIC MIT. At 8:55pm an email was kicked back with an undeliverable message from the email. The email used for contact was cwclark@cwcpetro.com which is the current email on file for the operator with the ECMC as of 4/10/26 6:11pm.

Location

Lease Road:			
Type	Access		
comment:	Access off of CR 17		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by fiberglass shed		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:		Date:	

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Entire location is used as a storage facility for unused equipment. See attached photos		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Triplex pump, electric circ pump, filter pots inside metal shed		
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	

PRODUCED WATER	4	300 BBLs	FIBERGLASS AST		39.817980,-102.488590
Comment:		4 water disposal tanks			
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 296428 Type: WELL API Number: 125-11298 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: Operational Violation Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>-2" Hg</u>	Previous Test Pressure _____	MPP _____
	(e.g. 30 psig or -30" Hg)		Inj Zone: <u>LKMR</u>
TC:	Pressure or inches of Hg <u>0 PSIG</u>	Previous Test Pressure _____	Last MIT: <u>01/20/2021</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	AnnMTReq: <u>NO</u>

Comment: CASING HAD A LIGHT BLOW, DIED IMMEDIATELY. TBG HAD 2" Hg. MASTER VALVE IS OPEN AT TIME OF INSPECTION.

Last MIT was conducted on 1/20/21. Well is past due for a 5 Year UIC MIT.

Corrective Action: Submit proper 10 day notice for MIT Date: 04/17/2026
Perform MIT per Rule 417.a. (1)

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Location is mostly vegetated over with some gravel around the truck loading area. There is fine sandy areas on both the east and west side of location

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404616294	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511758
715204292	location photos showing existing tanks and equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511757