

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2026

Submitted Date:

04/10/2026

Document Number:

721100299

FIELD INSPECTION FORM

Loc ID 311886 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 18 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	
Natural, Mach		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267797	WELL	SI	08/01/2025	CBM	067-08807	ARVIL BROWN 3	PR

General Comment:

On Monday, April 6, 2026 at 11 AM, southwest compliance inspector James Blair performed a location inspection and audit of the Simcoe Avril Brown N33N9W 15SWNE Location which contains the Simcoe Avril Brown 3. (Abundance Energy Avril Brown 1A, and Avril Brown DK 1A-R which share this location). Corrective actions pertaining to storm water BMPs and the Simcoe produced water tank label were observed. Inspection photos are linked in the attachments section.

Location			
Lease Road:			
Type	Main		
comment:	Water is diverting from county road onto location. A long term solution to this problem will require working with the designated road authority to maintain the road in such a way that water from the road no longer flows onto the pad. See photos 13 through 22. See stormwater section for related CA's.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Simcoe Avril Brown 3. East side of pad entrance. Photo 1. Sign still indicates "BP America"		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Simcoe 970-247-6196 (number works for Simcoe, previously conconfirmed). Emergency 911.		
Corrective Action:			Date:
Good Housekeeping:			
Type	DEBRIS		
Comment:	Non functional straw wattle debris at north end and south end of pad. Dispose of straw wattle debris that cannot be reused. Photos 14, 18.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Simcoe wellhead - Cattle panel.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Solar telemetry.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On Simcoe heated separator		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	accessible		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Simcoe on north end of pad.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Simcoe - cal. date 07/14/2025		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	4 rig markers, 2 rig anchors found on north end, other two are presumably buried next to markes on south end of pad.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		27.106958,-107.809896
Comment:	Simcoe Tank. Label lacks number of BBLs volume. Photo 6.				
Corrective Action:	Properly label tank to comply with 605.h				Date: 05/11/2026

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	Not indicated
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 267797 Type: WELL API Number: 067-08807 Status: SI Insp. Status: PR

Producing Well

Comment: PR. Separator is audibly operating.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/12/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: accessible

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					
Berms	Fail	Berms	Fail			
Compaction	Pass	Compaction	Pass			
Ditches	Fail	Ditches	Fail			
Gravel	Pass	Gravel	Pass			
Rip Rap	Pass					

Comment: Water flows down the access road (Black Hawk Trl), & diverts off road & onto the location. Sediment has filled up the run-on diversion ditch, downcut the associated berm, & undercut straw wattles, so stormwater flows directly onto pad at Abundance meter run shed, & deposits fan of sediment, at S. end of the pad. At N. end of pad, there is evidence of erosion where water exits the pad, and sediment carried off site into a grassy area nonfunctional straw wattles. Long term solution will require coordination with the designated road authority for Blackhawk trail to address the water diversion. Address issue prior to mobilizing equipment for plugging and abandonment.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C and minimize stormwater run-on and flowing through location and associated sediment migration.

Date: 05/25/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Corrective actions were identified pertaining to the Simcoe tank labels and stormwater BMPs. Photos are linked in the attachments section.	blairj1	04/07/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404616098	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511640
721100310	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511638