

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2026

Submitted Date:

04/10/2026

Document Number:

721100301

FIELD INSPECTION FORM

Loc ID 311895 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10840
Name of Operator: ABUNDANCE ENERGY SERVICES LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Findings:

- 29 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Abundance		aprice@abundance-energy.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Abundance		jepugh@abundance-energy.com	
Blair, Jamie		jamie.blair@state.co.us	
Abundance		sjbcompliance@abundance-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89106	WELL	PR	08/15/2007	GW	067-08210	A H TERRELL 1A	PR
282114	WELL	PR	06/19/2018	CBM	067-09094	IGW 106	PR
436554	WELL	PR	01/24/2018	CBM	067-09907	IGW 152	PR

General Comment:

At 16:00 hours on April 7, 20206 southwest compliance specialist Jamie Blair performed an producing well compliance inspection and audit on this location. It has 3 wells. AH Terrell #1A, IGW #106, and IGW #152. A corrective action was identified for IGW #106. The meter run calibration card indicated the last calibration was on 1/24/2025. Photos are linked in the attachment section of this report.

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Terrell		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	well gas 152 and 106.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	152 and 106		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	106 and 152 separator stacks.		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	4 other acnchors and markers from previous inventory not found. Presumably removed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Solar telemetry at 152 meter shed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	2 meter run sheds. Terrell and IGW 106 meters in shed on north side. IGW #152 on south side IGW 106 - Cal 1/24/2025 out of date. Photo 13. AH Terrell 1A - 02/04/2026 - OK IGW-152 - 01/09/2026 - OK AH Terrell #1A MV Cal 2/4/26 IGW #152 Cal. 1/19/2026.		
Corrective Action:	Conspicuously display calibration record documenting calibration within last year to comply with rule 430.d.	Date:	05/11/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		37.100711,-107.818501
Comment:	Tank looks relatively new. Hatch appears closed from base. Containment adequate.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:				plastic liner in appears functional.		
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV STEEL		37.100998,-107.818417	
Comment:				Paint is inadequate and shows signs of corrosion. Bare metal is becoming exposed in places. Photo 14. Operators should inspect and maintain equipment in good condition at regular intervals to stay in compliance with 609.b.		
Corrective Action:						Date:

Paint	
Condition	Inadequate
Other (Content)	
Other (Capacity)	40 BBL
Other (Type)	

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:	
Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 89106 Type: WELL API Number: 067-08210 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/25/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: accessible
 Corrective Action: _____ Date: _____

Facility ID: 282114 Type: WELL API Number: 067-09094 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/28/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: accessible
 Corrective Action: _____ Date: _____

Facility ID: 436554 Type: WELL API Number: 067-09907 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/28/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: accessible
 Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Compaction	Pass	Compaction	Pass			
Berms	Pass					
Gravel	Pass	Gravel	Pass			
Ditches	Pass					
Waddles	Pass					

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Corrective actions for exposed wire by wellhead and display of meter calibration date on 106 well. Tank conditions and labels for PBV produced water tank. See photos linked in attachments section.	blairj1	04/07/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404616220	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511688
721100311	Inspection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511685