


Inspection Photos
Location Name: Simcoe State 01-36; 35-08 #3
Location ID: API 05-067-08323



Energy & Carbon Management Commission
La Plata County
+37.262611, -107.691840
348° N
Apr 16, 2026 at 4:01:08 PM



Energy & Carbon Management Commission
La Plata County
+37.262338, -107.692019
5° N
Apr 16, 2026 at 4:00:32 PM

1. Well sign

2. Well location overview.

Inspection Photos
Location Name: Simcoe State 01-36; 35-08 #3
Location ID: API 05-067-08323



3. Wellhead behind cattle panel fence.

4. Wellhead.

Inspection Photos
Location Name: Simcoe State 01-36; 35-08 #3
Location ID: API 05-067-08323



5. Production equipment.

6. Solar telemetry.

Inspection Photos
Location Name: Simcoe State 01-36; 35-08 #3
Location ID: API 05-067-08323



7. Meter run shed.

8. Horizontal heated separator.

Inspection Photos
Location Name: Simcoe State 01-36; 35-08 #3
Location ID: API 05-067-08323



9. 95 BBL PBV steel tank with secondary containment.

10. Reclamation vegetation.

Inspection Photos
Location Name: Simcoe State 01-36; 35-08 #3
Location ID: API 05-067-08323



11. Sediment trap and ditch on east side of pad.

12. Down rig anchor marker in SE corner in reclamation vegetation.

Inspection Photos
Location Name: Simcoe State 01-36; 35-08 #3
Location ID: API 05-067-08323



13. Cut slope next to location access road near entrance.

14. Ditch and berm on west side of pad.