

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 13-26 Pad

Location ID: 334393



Photo # 520 From entrance to location

Photo # 521 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 13-26 Pad

Location ID: 334393



Photo # 522 Location

Photo # 523 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 13-26 Pad

Location ID: 334393



Photo # 524 Location




Photo # 525 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 13-26 Pad

Location ID: 334393





Photo # 526 SPECIALTY RESTAURANTS SG 413-26 plunger lubricator replaced

Photo # 527 SPECIALTY RESTAURANTS SG 413-26 plunger lubricator replaced