

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HEFLEY, M E #8X

Location ID: 315552

Date: 04/7/2026



Photo # 4186 Entrance to location



Photo # 4189 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HEFLEY, M E #8X

Location ID: 315552

Date: 04/7/2026



Photo # 4192 Sign lacks public road used to access the well

Photo # 4198 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HEFLEY, M E #8X

Location ID: 315552

Date: 04/7/2026



Photo # 4200 Location



Photo # 4202 Loose barbed wire fencing on location/wildlife hazard

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HEFLEY, M E #8X

Location ID: 315552

Date: 04/7/2026



Photo # 4204 Loose barbed wire fencing on location/wildlife hazard



Photo # 4205 Loose barbed wire fencing on location/wildlife hazard

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HEFLEY, M E #8X

Location ID: 315552

Date: 04/7/2026



Photo # 4206 Debris



Photo # 4207 Debris