

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404625828

Date Received:
04/20/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:
5 of 6 CAs from the FIR responded to on this Form
5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>ECMCInspectionReports@flywheelenergy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 719500996
Inspection Date: 03/18/2026 FIR Submit Date: 03/31/2026 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335750

Location Name: TEXACO-65S97W Number: 35NWNE County: _____
Qtrqtr: NWNE Sec: 35 Twp: 5S Range: 97W Meridian: 6
Latitude: 39.574397 Longitude: -108.240680

FACILITY - API Number: 05-045-00 Facility ID: 335750

Facility Name: TEXACO-65S97W Number: 35NWNE
Qtrqtr: NWNE Sec: 35 Twp: 5S Range: 97W Meridian: 6
Latitude: 39.574397 Longitude: -108.240680

CORRECTIVE ACTIONS:

2 CA# 211979

Corrective Action: Comply with CECMC wildlife safety rules. Date: 04/06/2026

Response: CA COMPLETED Date of Completion: 04/16/2026

Operator Comment: Wildlife egress has been installed in the wellhead cellars. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

3 CA# 211980

Corrective Action: Maintain fencing.

Date: 04/08/2026

Response: CA COMPLETED

Date of Completion: 04/16/2026

Operator
Comment: Fencing at wellheads has been repaired. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

4 CA# 211981

Corrective Action: Maintain fencing.

Date: 04/08/2026

Response: CA COMPLETED

Date of Completion: 04/16/2026

Operator
Comment: Fencing at separators has been repaired. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

5 CA# 211982

Corrective Action: Remove debris from location.

Date: 04/08/2026

Response: CA COMPLETED

Date of Completion: 04/16/2026

Operator
Comment: Debris has been removed. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

6 CA# 211983

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.

Date: 04/08/2026

Response: CA COMPLETED

Date of Completion: 04/16/2026

Operator
Comment: Open ended load line has been plugged. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

CA #211979: Wildlife egress has been installed in the wellhead cellars. Corrective Action complete.
CA #211980: Fencing at wellheads has been repaired. Corrective Action complete.
CA #211981: Fencing at separators has been repaired. Corrective Action complete.
CA #211982: Debris has been removed. Corrective Action complete.
CA #211983: Open ended load line has been plugged. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 4/20/2026 8:00:46 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files