

# Inspection Photos

API: 061-06847

Operator: MULL DRILLING COMPANY

Inspection Date: 4/15/2026

County: KIOWA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Center of the location facing north.



## Inspection Photos



**Photo 2.** Facing west. There is a livestock tank located approx. 375' east of the abandoned well site..



## Inspection Photos



**Photo 3.** Facing west toward the location.



## Inspection Photos



**Photo 4.** Facing southwest at the location. The plugged and abandoned well is located within the constructed corral area.



## Inspection Photos



**Photo 5.** Facing south at the west side of the location adjacent to the corrals. There are perennial grasses in this area.



## Inspection Photos



**Photo 6.** Southeast corner facing northwest toward the location. There are perennial grasses in this area. The plugged and abandoned well is located within the constructed corral area.

