

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305



Photo # 8432 From entrance to location

Photo # 8433 Sign at start of spur road to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305




Photo # 8434 Battery signage



Photo # 8435 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305



Photo # 8436 Location



Photo # 8437 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305




Photo # 8438 Location




Photo # 8439 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305



Photo # 8440 Wildlife protection for methanol tank containment needs maintenance

Photo # 8441 Wildlife protection for methanol tank containment needs maintenance

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305




Photo # 8442 PRV vent lines on separator do not comply with CECMC pressure safety device rules

Photo # 8443 Weeds in secondary containment

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305



Photo # 8444 Weeds in secondary containment



Photo # 8445 Weeds in secondary containment

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305



Photo # 8446 Weeds in secondary containment



Photo # 8447 Damage to secondary containment

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad

Location ID: 383305



Photo # 8448 Damage to secondary containment