

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2026

Submitted Date:

04/20/2026

Document Number:

708908976

FIELD INSPECTION FORM

Loc ID 383305 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 27 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
LARAMIE ENERGY		cogccnotifications@laramie-energy.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	
Heil, John		john.heil@state.co.us	
Gaasche, Emily		emily.gaasche@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289507	WELL	PR	11/28/2008	GW	045-13795	LOGAN WASH 797-23-45AX	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at start of spur road to location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/1-800-891-6191		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Small amount of weeds in secondary containment - please refer to photo log		
Corrective Action:			Date:
Type	OTHER		
Comment:	Wildlife protection for methanol tank containment needs maintenance		
Corrective Action:	Comply with CECMC Rule 602		Date: 04/27/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Chemical tank containment - hog panels & pipe rail fence		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels & pipe rail fence		
Corrective Action:			Date:

Equipment:				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Pressure transducer located on bradenhead			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Chemical tank			
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:	Well on plunger lift			
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Dehydrator	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Other	# 2			
Comment:	PRV vent lines on separator do not comply with CECMC pressure safety device rules			
Corrective Action:	Comply with CECMC Rule 608			Date: 04/27/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

METHANOL	1	<50 BBLs	STEEL AST			
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity) 500 gal						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment:		Separate containment				
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	HEATED STEEL AST			
Comment:		Tank equipped with telemetry				
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						
Comment:		Damage to secondary containment - please refer to photo log Centralized containment				
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST			
Comment:		Tanks equipped with telemetry				
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						

Comment:	Damage to secondary containment - please refer to photo log Centralized containment	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 289507 Type: WELL API Number: 045-13795 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Please refer to FORM 5 DRILLING COMPLETION REPORT document # 1928495 & FORM 5A COMPLETED INTERVAL REPORT document # 1928496 - Wellbore diagram inaccurate/not in compliance with CECMC Rule 420

Corrective Action: Comply with CECMC Rule 420 & submit accurate wellbore diagram via FORM 4 SUNDRY or FORM 17

Date: 05/20/2026

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small amount of light compaction
		Gravel				Sparse to none
		Ditches				
		Culverts				
Gravel						Sparse to none in most areas
		Drains				
				Material Handling And Spill Prevention		Chemical tank containment
		Berms				
		Retention Ponds				
Berms						
		Check Dams				
Other						
		Rip Rap				
		Compaction				Light compaction in some sections
		Sediment Traps				

Comment: [1. Soil stockpile in the interim area - Please refer to photo log \(Referred to ECMC Reclamation Group\)](#)
[2. Chemical tank containment approximately 3/8 full of fluid/BMP may need maintenance in the near future](#)
[3. Some signs of lack of stabilization on cut slope near tank battery](#)

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 04/10/2026 at approximately 15:56 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at LARAMIE ENERGY LLC Logan Wash 797-23-45AX Pad Location # 383305 in Garfield County Colorado. Location is within Black Bear Habitat area. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Housekeeping - Wildlife protection for methanol tank containment needs maintenance - Comply with Rule 602 with a CA date of 04/27/2026 2. Equipment - PRV vent lines on separator do not comply with CECMC pressure safety device rules - Comply with Rule 608 with a CA date of 04/27/2026 3. Inspected Facilities - LOGAN WASH 797-23-45AX wellbore diagram inaccurate - Comply with Rule 420 with a CA date of 05/20/2026 <p>Comments -</p> <p>Housekeeping -</p> <ol style="list-style-type: none"> 1. Small amount of weeds in tank battery secondary containment <p>Tanks & Berms -</p> <ol style="list-style-type: none"> 1. Damage to secondary containment <p>Stormwater -</p> <ol style="list-style-type: none"> 1. Soil stockpile in the interim area - Referred to ECMC Reclamation Group 2. Chemical tank containment approximately 3/8 full of fluid/BMP may need maintenance in the near future 3. Some signs of lack of stabilization on cut slope near tank battery <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p>	smelserw	04/20/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908977	Inspection/Audit 708908976 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7520086
708908978	Inspection/Audit 708908976 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7520088