

# Inspection Photos

API: 061-06844

Operator: JETTA OPERATING COMPANY

Inspection Date: 4/15/2026

County: KIOWA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest at the beginning of the access road. The cattle guard was never removed and is not attached to the fence line.



## Inspection Photos



**Photo 2.** Facing southwest along the access road near the location. There are areas bare of vegetation along the former road.



## Inspection Photos



**Photo 3.** Facing south along the access road near the location. There are areas bare of vegetation along the former road.



## Inspection Photos



**Photo 4.** Facing south along the access road near the location. There are areas bare of vegetation along the former road.



## Inspection Photos



**Photo 5.** Center of the location facing south. The location has not established vegetation and is mostly bare soils.



## Inspection Photos



**Photo 6.** Center of the location facing east. The location has not established vegetation and is mostly bare soils.



## Inspection Photos



**Photo 7.** Center of the location facing north. The location has not established vegetation and is mostly bare soils.



## Inspection Photos



**Photo 8.** Center of the location facing west. The location has not established vegetation and is mostly bare soils.



## Inspection Photos



**Photo 2.** Southeast corner of the location facing west.



## Inspection Photos



**Photo 2.** Southeast corner of the location facing northwest



## Inspection Photos



**Photo 2.** Facing south toward the surrounding undisturbed reference area which consists of native Blue grama, Sand dropseed, among other species.

