

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 44-27 Pad

Location # 334113




Photo # 138 From entrance to location

Photo # 139 Battery sign

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 44-27 Pad

Location # 334113



Photo # 140 Location

Photo # 141 Location



# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 44-27 Pad

Location # 334113



Photo # 144 Location



Photo # 145 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 44-27 Pad

Location # 334113



Photo # 4719 From inspection/audit 708908653 conducted on 03/03/2026 - Open ended load line

Photo # 146 Open ended load line

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 44-27 Pad

Location # 334113



Photo # 4720 From inspection/audit 708908653 conducted on 03/03/2026 - Open ended load line

Photo # 147 Open ended load line

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 44-27 Pad

Location # 334113



Photo # 4721 From inspection/audit 708908653 conducted on 03/03/2026 - PRV vent line does not comply with CECMC pressure safety device rules

Photo # 148 PRV vent line does not comply with CECMC pressure safety device rules

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 44-27 Pad

Location # 334113





Photo # 4722 From inspection/audit 708908653 conducted on 03/03/2026 - PRV vent line does not comply with CECMC pressure safety device rules

Photo # 149 PRV vent line does not comply with CECMC pressure safety device rules