

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #33AX

Location ID: 315790

Date: 04/8/2026



Photo # 4281 Entrance to location



Photo # 4282 Location

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #33AX

Location ID: 315790

Date: 04/8/2026




Photo # 4284 Wellhead sign lacks public road used to access the well

Photo # 4288 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #33AX

Location ID: 315790

Date: 04/8/2026



Photo # 4291 Location



Photo # 4293 Location