

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #30AX

Location ID: 315771

Date: 04/8/2026



Photo # 4309 Entrance to location



Photo # 4310 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #30AX

Location ID: 315771

Date: 04/8/2026



Photo # 4311 Wellhead sign lacks public road used to access the well

Photo # 4315 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #30AX

Location ID: 315771

Date: 04/8/2026



Photo # 4319 Location



Photo # 4321 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #30AX

Location ID: 315771

Date: 04/8/2026



Photo # 4326 Debris



Photo # 4327 Debris

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #30AX

Location ID: 315771

Date: 04/8/2026



Photo # 4328 Debris

Photo # 4329 Debris

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #30AX

Location ID: 315771

Date: 04/8/2026



Photo # 4330 Debris



Photo # 4331 Debris

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #30AX

Location ID: 315771

Date: 04/8/2026



Photo # 4333 Debris

Photo # 4334 Debris

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #30AX

Location ID: 315771

Date: 04/8/2026



Photo # 4340 Debris