

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/15/2026

Submitted Date:

04/21/2026

Document Number:

715204304

FIELD INSPECTION FORM

Loc ID 321880 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 51065
Name of Operator: LOEB LLC* HERMAN L
Address: P O BOX 838
City: LAWRENCEVILLE State: IL Zip: 62439

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---------------------------|---------|
| Beasley, Nolan | | nolan.beasley@state.co.us | |
| Quint, Craig | | craig.quint@state.co.us | |
| Pelton, Shane | 620-617-5870 | shane@loeboil.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 208311 | WELL | IJ | 06/19/2011 | ERIW | 017-07246 | COX V 2 | AC |

General Comment:

[SE Compliance Specialist Brian Welsh conducted a Routine UIC Inspection](#)

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Trail through farm ground | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by wellhead | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Pipe fence around wellhead | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Metal panels around cathodic rectifier and electric panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 208311 Type: WELL API Number: 017-07246 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

| | | | |
|------------|---|------------------------------|-----------------------------|
| Inj./Tube: | Pressure or inches of Hg <u>135 PSIG</u> (e.g. 30 psig or -30" Hg) | Previous Test Pressure _____ | MPP _____ |
| TC: | Pressure or inches of Hg <u>0 PSIG</u> | Previous Test Pressure _____ | Inj Zone: <u>MRRW</u> |
| Brhd: | Pressure or inches of Hg _____ | Previous Test Pressure _____ | Last MIT: <u>03/23/2022</u> |
| | | | AnnMTReq: <u>NO</u> |

Comment: CASING HAD A STRONG BLOW, DIED IMMEDIATELY. TBG IJ @ 135 PSIG

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | Other | Pass | | | |

Comment: Location and access are farmed over in wheat stubble

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---|
| 715204365 | location photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7522635 |